

Edward F. Wortmann, SP-1

Charles D. Blackwell, Alt. Leader Gen. Monitoring Section, H-1 CONTAMINATED TRAILERS FROM OVERSEAS TESTS.

H-1

410665

BEST COPY AVAILABLE

Trailers bearing the following numbers: J-16-3, J-16-6, J-15-5, J-16-8 and J-16-4, were monitored for contamination and all were found to have contamination of varying degrees. The interior of the trailers are physically dirty and should be washed at our decontamination pit as per telephone conversation on June 28, 1954. The trailers contain sand and dirt from overseas that should decontaminate without too much effort to a very low level.

According to information from Ben Meadows of J-Division, the trailer exteriors have already been scrubbed so the possibility of removing further contamination short of sand-blasting is very unlikely. Swipes were made of the hottest spots and no contamination would rub off. If sandblasting is used to clean the trailers before pointing, approved respirators should be worn as much from sand-blasting effects as from the results of contamination. We feel that the contamination presents no health hazard, but that it is desirable to avoid even small amounts of contamination whenever possible. It would probably be wise to inform personnel who will be working on the trailers of the contamination levels so that necessary steps can be taken. Below are a list of readings taken with SM-3 beta-gemma survey instruments.

Trailer No.	Position	Bets + Gamma	<u>L</u>	Gemma
J-16-3	Sides .5 -	2 mr/hr B & G 4 mr/hr B & G .05 - 3 mr/hr F 1 mr/hr B & G	3 & G	.5 mr/hr G .15 mr/hr G .15 mr/hr G .05 mr/hr G
J-16- 6	Sides .5 -	7 mr/hr B & G 6 mr/hr B & G .05 - 2 mr/hr I - 2 mr/hr B & G	3 & G	.15 mr/hr G .15 mr/hr G .15 mr/hr G .05 mr/hr G
J-15-5	Roof .1 - 'Sides .05 '	7 mr/hr B & G - 3 mr/hr B & G .05 - 1.5 mr/hr - 1.5 mr/hr B &	r B & G	.15 " " .1 mr " .1 mr/hr G .05 mr/hr G
J-16-8	Roof .1 - Sides .05 Under Side Outside O	.5 - 1 " "	W. Staure	.1 mr/hr G .08 m m m .05 m m m .05 m m m .05 m m m .05 00 m
			10-7-20	

June 28, 1954

-2-

contd.

Trailer No.	Position	Beta + Garma		Gamma
J-16-4	Roof .1-6 m Sides .05 - Under Side Inside .1 -	2 mr/hr B & G .05 - 2 mr/hr B & G	,	.15 mr/hr G .08 mr/hr G .15 mr/hr G .15 mr/hr G

Original Signed by CHARLES D. BLACKWELL

Charles D. Blackwell Alt. Leader Gen. Monitoring, H-1

CDB:mg

cc: Dean Meyer Files

> COPIED/DOE LANL RC

ED/DOE RC

7